## EDO-AIRE MITCHELL

AUTOMATIC FLIGHT SYSTEMS

AK514



EDO-AIRE MITCHELL
MINERAL WELLS, TEXAS

(14 VOLT SYSTEM)

### AK514

#### NOTICE TO THE INSTALLER

The Approval of the installation of this system is not applicable to specific aircraft having other previously approved modifications, unless it is determined the interrelationship between this change and the other approved modifications will introduce no adverse effect upon the airworthiness of the aircraft.

#### **AUTOPILOT R.F.I. INTERFERENCE**

Due to the variety and hi-power of radio equipment often found in today's General Aviation Aircraft, there exists a potential radio transmission interference problem with other equipment in the aircraft. Because of this potential, the autopilot system is designed and constructed with R.F. shielding to prevent interference however, installation combinations can occur wherein minor interference is possible.

R.F.I. interference from radio transmissions usually are manifest in one of two ways, either by interference with the VOR deviation needle display or by causing the autopilot flight path to be displaced during transmissions.

The most common interference causes the VOR deviation needle to jump or swing while the transmitter is being keyed. This type of interference affects the autopilot only in radio coupled modes as the autopilot is coupled to the VOR indicator meter movement and therefore, sees any needle movement as a command. VOR needle interference is sometimes found to be wholly within the NAV - COM set, that is, radiation of conduction of transmission energy from the transmitter to the VOR receiver internally. When this is the case, there is little the installation technician can do to overcome the condition other than contact the field representative of the company involved for advice.

A much less common interference type is one in which radio transmissions affects the roll of pitch axis of the autopilot directly. This occurence is caused by R.F. energy being radiated into the autopilot system and there being detected and fed as a signal to one or more of the autopilot

command channels. This problem is usually found only in aircraft equipped with high output power transmitters and varies with antenna types and mounting locations. The reflected power or standing waves on the antenna cable is probably the greatest single source of this trouble, however, an antenna located so it radiates into the cabin ean also cause the problem. The effect of this interference on the aircraft flight path is usually an initial displacement and then resumption of the programmed flight path. The response is similar in both roll and pitch.

Often, due to the wave form of radio frequency energy and the wave length, (frequency) an interference problem will only be found on one or two isolated frequencies. In these cases simply moving the autopilot component suspected or the radio source by a few inches will correct the problem.

Occasionally a new autopilot installation will cause a deterioration in A.D.F. receiver operation quality. This is reverse of the previous problem wherein "noise" from the autopilot is transmitted to the radio. One source of "noise" in the autopilot is the 5KHZ oscillator in the amplifier. Oscillator noise can get into the A.D.F. system by both induction and radiation. A power buss common to both the autopilot and A.D.F. receiver is a good path for this type interference. If a separate power source corrects the problem then a filter, such as Mitchell part number 1A479, in one or both A+ leads will usually eliminate the interference. Radiation from autopilot cable and terminal ends, although very weak, can sometimes interfere with the A.D.F. receiver by radiation into the sense antenna, or loop, or both. additional distance betrouting providing

ween these items and additional shielding of the autopilot leads is usually best in these cases. Since the autopilot leads are already shielded, the most productive solution is usually routing.

An important area, often over looked, is the ground and ground path. It has been found in many aircraft that a considerable resistance builds up between adjacent sections of skin paneling and structure due to paint, primer, etc. This increases the resistance in the ground path for some equipment, which lowers the equipment tolerance to R.F.I. Sometimes it is adviseable to add a braided ground strap to the equipment to assure a good ground.

Ground loops developing in cable shielding and the aircraft due to the existance of a ground potential difference can also cause problems. In some cases it might be necessary to connect only one end of a shielded cable to ground or even to isolate the autopilot amplifier from ground.

In summary, if an interference between the autopilot system and one or more of the radios is determined to exist, then one or more of the following cures should be tried in an effort to eliminate the interference.

- Install a filter in one or all involved A+ leads.
- 2. Re-route antenna leads.
- 3. Re-route autopilot leads and cabling.
- 4. Relocate antenna.
- Relocate autopilot component Consult GADO office concerning approval of installation deviation.
- Add ground straps to affected component(s).
- 7. Eliminate ground from one end of long ground shielded leads.
- 8. Isolate autopilot amplifier from ground.

#### FIELD SERVICE RECORD CARD - INSTALLATION

We have endeavored through this installation manual to provide you with complete and accurate installation information. You can help us improve and up-date this manual and the installation kit by reporting any errors, omissions, or discrepancies on this reporting sheet.

Fill out as completely as possible. Fold along the dotted lines and affix a stamp to the pre-addressed side.

Thank you

Director, Flight Engineering EDO-AIRE MITCHELL Mineral Wells, Texas

AK Number		Date of Manual					
Aircraft Type and Model							
Your Name							
	our Company Name						
Phone Number: Area	CodeNumber	Extension					
Page		Discrepancies - Comments					
40							

Director, Flight Engineering EDO-AIRE MITCHELL PO Box 610 Mineral Wells, Texas 76067 EDO-AIRE MITCHELL P.O. Box 610 Mineral Wells, Texas 76067

#### REVISION REFERENCE SHEET

- Original Manual, AK514, Century I Autopilot, Bulletin No. 637 dated 11-8-74 for Grumman American Model AA-5B.
- Revision (1) dated 5-2-75, (Major Change)
  Added Grumman American Model AA-5 and removed A/P Interrupt Switch.
  Reference FECO 452.
- Revision (2) dated 7-29-75 (Major Change) Added Grumman American Model AA-5A. Reference FECO No. 517.
- Revision (3) dated 10-30-75 (Major Change)
  Included Autopilot Flight Manuals, P/N 68S296 for models AA-5 and AA-5A and P/N 68S297 for model AA-5B, in Placards Section of manual.
  Reference FECO No. 663.
- Revision (4) dated 12-6-76 (Major Change)
  Added POH Supplements. Reference FECO #1094.
- Revision (5) dated 2-21-78 (Major Change)
  Changed POH Supplements to Supplemental Flight Manuals. Reference FECO # 1667.

#### MASTER DWG LIST

FOR Century I - AK514

S.T.C. SA3031SW-D

DRAWING NO.	DESCRIP	TION	REVISIONS	DATE
DRAWINGS REQU	RED FOR THE INSTALLER TO	MAKE THE INSTALLAT	ION:	
637	Bulletin		(5)	2-21-78
69A873 69D875-2 69D932	Template for Turn and B		<b>-</b> В	
	Roll Servo Installation DEFINE THE DESIGN AND A		A	
1C363-1	Servo Outline Drawing 1		A A	
	200		•	
7C1267-1 7B1268-1	Bracket Roll Servo Inst Bracket Roll Servo Inst		_ A	
12A2I5	30C402-( ) Assembly Val Length (Inches) (Cent		G	Application of the second of t
-				
13A616 13A751	Placard, T & B Autopilot Serial Placard	d	A	
13A629	Placard	1	_	
13A845	Placard		-	
30B200 30C402-( )	Cable Assembly Cable Assembly for 52D75	5-3/4 on Century I	F B	
42A173-1	Cable Clamp Assy.		D	
52D75-3/4	Outline Drawing Turn and	d Bank	G	
93A363-1-373R	Servo Assembly Information 1C363-1-373R 12VDC, 7.2		A	
and the second				
MASTER DRAV	VING LIST REVISION	MITCHELL	INDUSTRIES	INC
Updated Master		MINERA	L WELLS , TEXA	AS
Revised Bulleting Revised 13A762-		TITLE		
Revised Bulleti	1, -, ,		7 T TAKEMAT LAME ON	
<del>                                     </del>	37. Removed 12A294,	CENTURY	I INSTALLATION	
	13A762-514, 13A762-514-1	CHECKED	I DRA	WING NO.
79D48. Added 1	3A751, 13A845,	B 1.		A750
93A363-1-373R	12-6-76	DATE:	men	
Rev. 637. Remov	red 52D75-13/-14. 2-21-78	DATE: 11-8-74	SHEET	1 of 1

#### TABLE OF CONTENTS

SECTION I. CENTURY I INSTALLA	TION																
Introduction	n		•						•		•					Page Page Page Page	1- 1- 1- 1- 1-
Component Weights and Current SECTION II.	C DIAIN	•	•	•	•	•	•	•	•		٠	•		•	•	rage	1-
Parts List			•	•	•	•		•	• 5.•	•		•	•	•	•	Page	2-2
Ground and Flight Checks (683	S92)		•	•			•	•				•	•	•		Page	3-1
SECTION IV.																	
Appendix															1	Page	4-7

#### SECTION I

#### INTRODUCTION

This installation manual is intended to facilitate proper installation of the Mitchell Century I. Before proceeding with the installation, read the manual and study the installation drawings carefully.

The Mitchell Century I is a light weight, all electronic stabilization system contained in two compact units, plus interconnecting wiring.

The panel mounted instrument contains the pictorial Turn and Bank, stabilizer electronics, optional tracker electronics, and tracker switching. The operating controls on the face of the instrument consists of two control knobs. The left knob controls the Roll Trim and the knob on the right side is the turn command control. The panel unit is available with either blue or gray mask, with or without internal lighting, and with or without tracker electronics in conjunction with the stabilizer electronics. The Roll Actuator is the other unit and it is mounted in the fuselage or wing as required by the particular aircraft installation. (See Roll Servo Installation.)

The installation hardware is packaged in individual group packages for each component installation. Open the group packages and inspect the parts individually to ensure a complete understanding of their purpose and location prior to beginning each installation.

EDO-AIRE MITCHELL Mineral Wells, Texas

#### TURN AND BANK 52D75-( )

#### PARTS GROUP I

Drawing No. 69A873

- 1. The Century I, Turn and Bank unit is mounted in the instrument panel in any available standard 3" instrument hole cutout in clear view of the pilot that provides adequate clearance behind the panel. The ideal location would be one that offers a minimum of parallax as viewed from the pilot seat. If the instrument replaces the original turn and bank instrument, it should be mounted in the same location.
- Using the cutout modification detail on Drawing No. 69A873 as a guide, modify the existing 3" dia. instrument cutout.
- 3. Remove the two control knobs from the front of the instrument and mount the instrument in the instrument panel. Use four 35226 screws. Use care not to jar or bump the instrument during installation as all gyroscopic instruments are delicate. Replace the control knobs.

CAUTION: Do not use mounting screws that extend into Turn and Bank more than 1/2".

- 1. The (item 1) 1C363-1-373R Roll Servo is mounted on lower end of the yoke support bracket directly below the fuel selector valve. Refer to Drawing No. 69D932.
- 2. To gain access to this area remove the royalite pedestal side panels.
- 3. Temporarily attach (item 3) 7B1268-1 bracket and (item 2) 7C1267-1 bracket to the (item 1) roll servo using four (item 8) 3S92 bolts, four (item 10) 4S134 washers and four (item 9) 2S38 nuts. Use Drawing No. 69D932 as reference for mounting the brackets to the servo.
- 4. Place the servo assembly near the lower end of yoke support bracket as shown on Drawing No. 69D932. Position the assembly so that the servo capstan is centered over the aileron cable. The left (outboard) edges of the brackets should be nearly flush with the edges of the yoke support bracket as shown on Drawing No. 69D932.
- 5. Using the five holes in the (item 2) and (item 3) brackets as a guide, mark and drill five .166 dia. (No. 19) holes in the yoke support bracket. It will be necessary to disassemble the brackets from the servo to mark all of the hole locations.
- 6. Attach (item 2) and (item 3) brackets to the yoke support bracket using five (item 5) 3S464 screws, five (item 6) 2S34 nuts and five (item 7) 4S205 washers.
- 7. Mount the servo to the brackets using four (item 8) 3S92 bolts, four (item 9) 2S38 nuts and four (item 10) 4S134 washers. (Hardware removed in Par. 5)
- 8. Loosen the cable guards on the servo. Rotate the capstan so the bridle cable pin hole is just fwd of bottom cable guard, approximately 160° from top cable guard, as shown on Drawing No. 69D932. Position the (item 4) 30B200 bridle cable so that the long end of cable (from pin) is aft and parallel to the aileron cable. Insert the bridle cable pin into the capstan hole and tighten set screw.
- \*9. With the aileron control in neutral position, wrap the short end of the (item 4) 30B200 bridle cable around the capstan 330°. This will bring the cable fwd. Attach the bridle cable to the aileron cable with one (item 11) 42Al73-1 cable clamp.
  - \*NOTE: Aileron cable should be clean and free from excessive oil or grease at points where cable clamp attachment is made.
- 10. Wrap the long end of the bridle cable approximately 390° aft around the capstan. Attach bridle cable to aileron cable using one (item 11) 42A173-1 cable clamp. NOTE: Move aileron control to the left stop (full travel). In this position the aft end of the forward cable clamp should clear the forward lower servo mount bolt by 1/8" to 1/4". If this clearance is not provided, reposition cable clamps as necessary to provide clearance. Exercise aileron control, check for binding or other interference.
- 11. Torque cable clamp bolts to  $55 \pm 5$  inch pounds with a minimum of .005" measured between clamp halves after torquing. Cable tension should be the same as the aileron primary cable tension.
- 12. Position the cable guards within 1/32" of the capstan O.D. and tighten.
- 13. Rotate aileron thru full travel and check for any binding or restriction of bridle cable or clamps that may contribute to unsafe conditions.

#### A WORD ABOUT THE TRACKER

If the Tracker option is installed in the Century I 52D75-4, consideration must be given to the Navigation Converters. The Century I Tracker is designed to operate with all Navigation Converters having an ARINC 1000 ohm meter movements. That is, full scale deflection of the left/right meter requires 150 microamps through a 1000 ohm load + left or + right (floating). The Tracker has a high impedance input of greater than 10 K ohms. Therefore, it's loading is negligible and need not be considered in selecting correct loading for the Navigation Converter.

NOTE: Before connecting autopilot check the capacity of the power source to determine the addition of autopilot will not adversely affect the electrical system. Refer to Advisory Circular 43.13-1A, Chapter 11, Section 2, Paragraph 428.

#### ELECTRICAL CABLE HOOK-UP

#### PARTS GROUP III

Drawing No. 69D875-2

The Century I is connected as shown on Drawing No. 69D875-2 and according to the code numbers on the cable ends.

All cables should be routed clear of flammable fluid and oxygen lines. Secure cables to airframe with AN742 cushion clamps within a maximum spacing of 18 inches to prevent damage and allow full freedom of controls. All open cable connections and interconnections, such as wristlock connectors and knife disconnect type connectors, shall be protected with a suitable insulating sleeve which shall be secured in accordance with good aviation wiring practices. Polyvinyl chloride sleeving material is an acceptable insulator. Ref. AC 43.13-1A, Chapter 11.

- 1. Route CD-47 of 30C402-5 cable harness with other aircraft wiring to the roll servo. Observe wiring practice as outlined in AC 43.13-1A. Connect CD-47 to the roll servo.
- 2. Connect large connector CD-92 to rear of the panel mounted 52D75-( ).
- 3. Connect CD-97 and CD-98 of 30C402-5 to + left and + right terminations of navigation converter when 52D75-4 is installed. Tie back and cover these leads when the 52D75-3 is installed.
  - 4. Connect ground lead of 30C402-5 to airframe ground.
  - 5. Mount the ON/OFF Switch (40S35) in the instrument panel in location accessible to pilot. A 1/4" hole is required for mounting. Placard 13A845 (Group IV) should also be installed under switch ring nut at this time.
- \*6. Install the circuit breaker provided, in the aircraft circuit breaker panel.
- 7. Connect CD-51 from cable assembly 30C402-5 to load side of circuit breaker.
- 8. Connect other side of circuit breaker to aircraft buss bar with No. 20, MIL-W-5086A wire not to exceed 6 inches in length.
- 9. Connect wire from ON/OFF switch (40S35) to load side of circuit breaker. This wire should also be No. 20, MIL-W-5086A.
- 10. Connect CD-50 to other side of ON/OFF Switch.
- 11. This completes the wiring, make sure all wiring is routed, insulated, and tied as outlined in Advisory Circular 43.13-1A.

\*NOTE: Mechanical Products Circuit Breaker Part No. 1600-019-050 may be used as an alternate for the Autopilot Circuit Breaker.

#### PLACARDS

#### PARTS GROUP IV

- 1. Apply placards 13A616 and 13A629 by the circuit breaker.
- 2. Placard 13A845 should have been installed in Step 5 (Electrical Cable Installation).
- 3. Install placard 13A751 "S/N" in the aircraft log book. This placard is used for autopilot warranty and service identification.
- 4. Remove the appropriate Supplemental Flight Manual from the back of this installation bulletin, fill in the blanks and place with the aircraft records or in the supplement section of the Pilot's Operating Handbook.

NOTE: The FAA Type Certificate Data Sheet for any particular aircraft will list the appropriate document and/or placards required for that aircraft.

WHEN: Placards are required use Supplemental Flight Manual.

#### COMPONENT WEIGHTS AND CURRENT DRAIN

#### \*1. COMPONENT WEIGHTS

COMPONENT	WEIGHT	ARM	MOMENT
Turn & Bank - 52D75-( )	2.4 lbs.		
Roll Servo - 1C363-1-373R	2.3 lbs.		
Cables	.5 lb.		

#### 2. CURRENT DRAIN

Maximum Servo Action 2.0 Amps

<sup>\*</sup>Does not include weight of brackets, attaching hardware, etc.

#### 5-02-75 Rev. 7-29-75 Rev. PARTS LIST 10-30-75 Rev. 12-06-76 Rev. EDO-AIRE MITCHELL CENTURY I MODEL AK514 PARTS LIST FOR 2-21-78 Rev. GRUMMAN AMERICAN MODEL AA-5, AA-5A AND AA-5B (14 VOLT SYSTEM) Item No. Part No. Description Spec. No. Qty. SECTION I. CENTURY I INSTALLATION GROUP I TURN AND BANK 1. 52D75-3/-4 Turn and Bank 12A73 & 12A145 1\_\_\_\_\_ (TSO) 35226 2. Screw AN505B6R8 GROUP II ROLL SERVO 1. 1C363-1-373R Roll Servo 12A94 (PMA) PMA 2. . 7C1267-1 Bracket 7B1268-1 3. PMA PMA Bracket 4. 30B200 Bridle Cable 35464 AN525-832-R8 5. Screw 6. 2534 AN365-832 Nut 7. 45205 Washer AN960-8 Bolt 8. 3592 AN3-4A 9. 2S38 AN365-1032 Nut 45134 10. Washer AN960-C10 11. 42A173-1 Cable Clamp PMA

SECTION II.

11-8-74

DATE

DATE

DATE

THIS (AK514) HARDWARE KIT CONSIST OF GROUPS
IN ACCORDANCE WITH HARDWARE PARTS LIST DATED
\*\*DENOTES PART OR COMPONENT PACKED SEPARATELY

ASSEMBLED BY

Q.C. INSPECTED BY

SHIPPING DEPT. INSP. BY

Item No.	Part No.	Description	Spec. No.	Qty.
		GROUP III ELECTRICAL CABLES		
1. 2. 3.	30C402-5 40S35 65S67	Cable Assembly Switch Circuit Breaker (3 Amp)	PMA PMA PMA	1 1
		GROUP IV PLACARDS		
1. 2. 3. 4. 5. 6. 7.	13A616 13A751 13A629 13A845 68S296-1 68S297-1 68S491-1-S 68S492-1-S	Placard, Turn & Bank Placard, S/N Placard, Century I Placard, ON/OFF Supplemental Flight Manual Supplemental Flight Manual Supplemental Flight Manual Supplemental Flight Manual	PMA PMA PMA PMA	

THIS (AK514) HARDWARE KIT CONSIST OF GROUPS	
IN ACCORDANCE WITH HARDWARE PARTS LIST DATED	REV.
**DENOTES PART OR COMPONENT PACKED SEPARATELY	
ASSEMBLED BY	DATE
Q.C. INSPECTED BY	DATE
SHIPPING DEPT. INSP. BY	DATE

#### SECTION III

#### GROUND AND FLIGHT CHECKS

#### Revision 12-06-71 Revision 2-21-74 Revision 5-18-76 Revision 11-5-76

#### CENTURY I AND TRACKER

The Century I Automatic Flight System has only two adjustments other than the normal controls. One is a trim centering adjustment potentiometer that is located on the rear of the panel mounted instrument unit. This potentiometer is used to center the trim knob during the initial ground check. The other adjustment is a roll servo threshold adjustment that should be made only in flight as necessary to match the amplifier threshold to the threshold of the servo motor.

#### PRE-FLIGHT

- 1. Check Century | Circuit Breaker IN.
- 2. Turn on aircraft master switch and listen for Gyro motor start in Turn and Bank instrument.
- 3. Turn Century I master ON/OFF switch ON.
- 4. Pull turn control knob (right side) out and rotate left and right. Observe the control wheel rotates left and right. Center turn control knob.
- 5. Rotate trim control knob (left side) left and then right and observe the control wheel turns left and right slowly. Place the trim control knob in the center of its travel. If the aircraft control wheel continues to slowly move left or right, then adjust the trim centering potentiometer on the rear of the instrument as necessary to stop all wheel movement.
- 6. Turn on the VOR receiver and tune a local station whose signal can be received on the aircraft. Rotate the OMNI Bearing Selector (O.B.S.) until the deviation needle centers. Push IN the turn control knob to actuate the electric tracker. Slowly rotate the O.B.S. to cause a full scale needle deflection left and then right. Observe that the aircraft control wheel follows the VOR deviation needle left and then right. Turn tracker OFF.
- 7. Override servo in both directions with aircraft control wheel manually.
- 8. Press "Autopilot Interrupt" switch on pilot's control wheel and rotate control wheel to check for servo disengagement.

  Release switch servo should re-engage. (This item not applicable to all installations, refer to installation data for applicability.)
- 9. Begin taxi with Century I ON- Century I should cause a control wheel deflection opposite to the direction of turn.

This completes the ground check portion. There are no specific initial in-flight checks required, other than normal operation. If at all possible the initial Flight Test should be conducted in calm air, as this makes an evaluation of performance much easier and more accurate. Some aircraft models might require that a servo threshold voltage adjustment be made to the 52D75 in order to match the servo amplifier electronic threshold to the starting voltage requirements of the individual servo motor used in the installation. A mismatched threshold is usually manifest by "Wing Rock" or control wheel "Jitter" if the threshold is too high or by roll overshoot or long term, slow, roll oscillations if the threshold is too low. Generally, no adjustment is required and an adjustment should not be attempted unless a threshold mismatch is known to exist, i.e. unless the test flight is conducted in perfectly smooth air it is almost impossible to determine in most cases, also some degree of roll overshoot is always present depending on the airspeed used.

If a threshold adjustment is deemed necessary, proceed as follows:

52D75 Units with serial numbers ending in the letter "D" or later.

- The roll threshold potentiometer is located directly in line with the top left instrument mounting screw, inside
  the instrument. Access to the potentiometer is made by removing the top left mounting screw and inserting a
  small, narrow blade, screw driver into the screw hole approximately (1) inch.
- 2. The potentiometer is a small, 20 turn trim pot, that is manufactured without stops. It should turn very easy throughout it's full range with the only indication of full travel being a slightly audible "click" each revolution once at full travel. If the pot is not easy to turn Do Not Apply Force To Turn It. Pull out the screw driver and re-insert in a different position. The screw hole is provided with a guide tube, however, it might be possible to get the screw driver blade wedged between the "pot" screw head and the guide tube. Forcing while in this position might result in damage to the pot. The pot is affixed to the amplifier circuit board.
- 3. The factory threshold adjustment procedures usually result in the "Pot" being within 3 turns of center. Adjust the pot in 1 turn increments until proper adjustment is obtained. If the roll oscillation is long term, the threshold pot should be tightened, (C.W.). If the roll oscillation is short term or if the control wheel jitters or is over active then the threshold must be reduced, turn the pot C.C.W. After adjustment replace the mounting screw removed in Step No. 1.

52D75 Units with serial numbers ending with no code letter or code letters A through C.


- 1. These units have the same trim potentiometer as the later units, however it is located in a different position on the circuit board, thereby making in-flight adjustment much more difficult. Shop adjustment can be made by reference to the 52D75 Overhaul Manual Paragraph 4.2.5.17 or an in-flight adjustment can be made as follows:
- 2. Remove the instrument from the instrument panel and place it in a suitable holding fixture that will allow operation in flight.
- Remove the cover from the instrument by removing the tape around the bezel and the single screw at the rear adjacent to the main connector.
- 4. Locate the Trim Pot (R25) located on the left circuit board about midway between the instrument face and the connector end. The pot is located at the top of the board and is oriented vertically, with the adjustment screw at the top. Note that there is another pot at the front of the circuit board, nearest the face plate. This is Not The Threshold Pot, Do Not Adjust.
- 5. Adjust the threshold as discussed in Paragraph 3 for units serial number "D" and later.
- 6. Replace sealing tape and cover and reinstall instrument in instrument panel after flight.

#### SECTION IV

#### APPENDIX

- 1. Drawing Package (Refer to Master Drawing List for contents)
- 2. S.T.C. Certificate
- 3. A.F.M. Supplement, Supplemental Flight Manual, Placard, or Pilot's Operating Handbook Supplement
- 4. R.F.I. Instructions

	If A.F.M. Supplement is required, remove and place in the Airplane Flight Manual.
X	If Supplemental Flight Manual is required, remove and place with aircraft records.
	If Placard is required, place on instrument panel in full view of the pilot.
	If Pilot's Operating Handbook Supplement is required, remove and place with Pilot's Operating Handbook.



#### MITCHELL INDUSTRIES CHECK SHEET & PACKING LIST

Type Cont I Sold To Julisticam	Kit No. AK514
Ship To Same	H. O. No. 44796 Date 4-23-79
PACKING LIST	CHECK
II AXIS	ROLL
A. H. 52D66 S/N D. G. 52D54 S/N S/N Cons. Amp. 1C385 S/N S/N S/N SILTER 1B440 S/N	Roll Center Horiz. at 2 <sup>0</sup> R L Roll Knob Center D. G. R L Man Bank R L Horiz. Output R L Right Command = Capstan Rotation
A. H. 52D67 S/N S/N S/N S/N S/N S/N S/N	PITCH
Console         1C404         S/N           Amplifier         S/N           Alt. Hold         1C407         S/N           Roll Servo         S/N           Pitch Servo         S/N           Filter         1B440         S/N	Horiz. Center Pitch Limits UP DN  Alt. Hold Up Command = Capstan Rotation  COUPLER TRIM
TRIM  Trim Sensor	Center Adj.
Coupler 1C388M S/N Glide Slope 1C493 S/N Trim Adpt. Box 1B552 S/N Back-up Sys. S/N Tracker S/N	COUPLER GROUP TRIM GROUP  1 1 2 2 3
T & B 52D75- S/N S/N S/N	BACK UP SYS. GROUP G/S GROUP
CENTURY GROUP	Warehouse & Shipping Initial
Warehouse & Shipping Initial         1.       7.         2.       8.         3.       9.         4.       10.         5.       11.         6.       12.	1

## 92A342

Page		1	of	1
3-	_			

EDO-AIRE MITCHELL							
Mineral Wells, Texas							
Drawn	By R.A. Date 12-13-77						
Apvd.	By E. Come Date 12-14-77						
Apvd.	By Date						
Anyd.	By LIALUN Date 12-14-77						

OEM	PAR	TS/F	PACKI	NG
		LICT		

Grumman

O.E.M. American

AK 514

No.

Documentation Issue
Type Set Polons

Spec. 92A342
No. 1ssue Change Date
Release FECO 1592 12-14

Apvd. By 1/12/10 Uate 12-14-7

92B339

Apvd. For Aircraft Models :

AA-5B

PMA Inspection Stamp :

Kit Assy. Spec. No.

Note: List SN Items First

ONTY.	P/N	DESCRIPTION	S/N
1	Bulletin No. 637	AK514 Installation Bulletin	
1	13A751	Placard, S/N	
1 1	68S72	Century I Operator's Manual	
1	68S78 -	Final Inspection Check Out-Sheet	
1	91S225	Warranty Validation Form	

Customer P.O. No. <u>18H54I39</u> Mitchell H.O. No. <u>44794</u>

Form 91S267

United States of America

Department of Transportation—federal Aviation Administration

### Supplemental Type Certificate

Number SA3031SW-D

This certificate, issued to

Mitchell Industries, Inc., dba

EDO-AIRE MITCHELL

P.O. Box 610

Mineral Wells, Texas 76067

certifies that the change in the type design for the following product with the limitations and conditions

therefor as specified hereon meets the airworthiness requirements of Fart 23 of the Federal Aviation

Regulations.

Original Product - Type Certificate Number: A16EA

Make: GRUMMAN AMERICAN

Model: AA-5, AA-5A, AA-5B

Description of Type Design Change:

Installation of Mitchell Automatic Flight System Model AK514 consisting of a Century I Autopilot with Optional Omni Tracker System according to Bulletin No. 637, Revision 5, dated 2-21-78 and Master Drawing List No. 87A750, Revision E, dated 2-21-78 (14 Volt System) and/or later FAA Approved revisions of the above data.

Limitations and Conditions: The following FAA/DAS Approved Supplemental Flight Manuals are required: P/N 68S296-1, dated 12-30-76 for Grumman American Models AA-5 and AA-5A, S/N 282 and below; P/N 68S297-1, dated 12-30-76 for Grumman American Model AA-5B, S/N 399 and below; P/N 68S491-1-S, dated 2-21-78 for Grumman American Model AA-5A, S/N 283 and Up, P/N 68S492-1-S, dated 2-21-78 for Grumman American Model AA-5B, S/N 400 and Up and/or later FAA Approved revisions of the above supplements.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the Federal Aviation Administration.

Date of application: 11-11-74

Sinterefisauance: 11-27-74

5-19-75; 8-4-75; 11-25-75;

12-30-76; 2-21-78 Revision 5

By direction of the Administrator

(Signature) HAROLD W. HOLDEMAN DAS STAFF COORDINATOR, DAS 2 SW

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

## SUPPLEMENTAL FLIGHT MANUAL FAA/DAS APPROVED FOR

**GRUMMAN AMERICAN MODELS AA-5** AND AA-5A, S/N 282 AND BELOW

No.	No.
Reg.	Ser.

No.
Ser.

The information in this manual is FAA Approved material which along with other documents is applicable to the operation of the airplane when modified by the installation of Edo-Aire Mitchell Century I Autopilot, Model AK514 installed in accordance with STC SA3031SW-D.

# LIMITATIONS

- Autopilot use prohibited above 150 MPH CAS.
  - Autopilot OFF during take-off and landing.

## PROCEDURES

# NORMAL OPERATION

- Engagement
- Toggle switch on instrument panel ON.
- Disengagement
- Toggle switch on instrument panel OFF.
  - Heading Changes
- Move trim knob on instrument for drift correction from a constant heading.
- Move turn command knob on instrument for right or left banked turns.
- OMNI Tracker
- Center turn command knob and push IN to engage tracker.

FAA/DAS APPROVED DATE: 12-30-76

Mineral Wells, Texas 76067 P. O. Box 610

EDO-AIRE MITCHELL

P/N 68S296-1

Trim knob - push IN for high sensitivity. (For Localizer Tracking)

Ь.

# **EMERGENCY OPERATION**

- In case of malfunction, inititally overpower manually to maintain aircraft control,
- Toggle switch on instrument panel OFF.
- Check Century I circult breaker reset, if necessary, to restore turn and bank instrument operation.
- In climb, cruise or descent configuration a malfunction with a 3 second delay in recovery initiation results in 50° bank and 355' altitude loss. Maximum altitude loss measured at 150 MPH CAS in a descent.
- ay in recovery initiation results in 180 bank and 40' altitude In approach configuration a malfunction with a 1 second de-5

# PERFORMANCE

No change

EDO-AIRE MITCHELL James L. Irwin DATE: 12-30-76 P/N 68S296-1 APPROVED DAS 2 SW

Page 2 of 2